

## Restoration Estimates by Area\*

### **Oct. 4, midnight: (except isolated pockets due to extreme damage):**

- Southern Caldwell County and Alexander County communities **except**: Hwy 18 toward Kings Creek, Globe, Edgemont, Mortimer, Johns River Loop, Staircase.

### **Oct. 5, midnight: (except isolated pockets due to extreme damage):**

- Alleghany County communities

### **Oct. 6, midnight (except isolated pockets due to extreme damage):**

- Watauga County communities **except**: Howard's Creek, Todd, Blowing Rock, Hwy 221 (Gragg community) Shulls Mill, Beech Creek, Peoria, Bethel, Kellersville, Valley Crucis, Elk—Triplett , Rominger, Laurel Creek
- Ashe County communities **except**: Creston, Lansing, Shatley Springs, Big Laurel, Laurel Springs, Hwy 88 toward Sutherland, Big Horse Creek, Big Springs, Crumpler, Old Mill Creek, Timber Ridge, White Oak, Vannoy Rd., Sheets Gap

### **Oct. 11, midnight (these are the most severely damaged areas):**

#### **Watauga County:**

Shulls Mill  
Beech Creek  
Peoria  
Bethel  
Kellersville  
Valle Crucis  
Elk—Triplett  
Rominger  
Laurel Creek

#### **Ashe County:**

Creston  
Lansing

Shatley Springs  
Big Laurel  
Hwy 88 toward Sutherland  
Big Horse Creek  
Big Springs  
Crumpler  
Old Mill Creek  
Laurel Springs

**Caldwell County:**

Globe  
Edgemont  
Mortimer  
Johns River Loop  
Hwy 18 towards Kings Creek

**Avery County communities**

**Wilkes County:**

Timber Ridge  
White Oak  
Vannoy Rd.  
Sheets Gap

***\*Some isolated pockets will take longer due to the most significant damage.***